Work Order ID 60973 Tuesday, August 03, 2010 9:21:12 AM Item ID: D4017-5 Page 1 **Revision ID:** Accept Item Name: Setup Start Hinge Rib Start Date: 8/4/2010 Start Qty: 2.00 Stop Required Date: 8/6/2010 Req'd Qty: 2.00 Cust Item ID: Reference: Customer: Approvals: Process Plan: MF Date: 10-8-03 Tooling: Run Start Date: Date: \_\_\_\_\_ SPC (Y/N): Sequence ID/ Date: Stop Operation Work Center ID Description Set Up/ Tool ID Tool # Plan Draw Nbr **Run Hours** Accept Revision Nbr Reject Reject Insp. Code Qty Qty Number D4017 Stamp В 100 0.00 Large Fab Memo Large Fab 0.00 1- Cut tube as per dwg D4017 SAD 2- Deburr and remove identify marks 10-08-04 110 QC5- Inspect part completeness to step on W/O 0.00 810/08/04 Memo Quality Control 120 Identify as per dwg & Stock Location: 0.00 Packaging Memo Packaging 10-08-04 0.00

W/O:			WO	RK ORDER CHAN	GES	· · · · · ·					
DATE STEP		PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto		
Part No: PAR #: _		PAR #:	Fault Category: N			NCR: Yes No DQA:			Date:		
	Res	solution:	Disposition	n:	QA	N/C C	losed:	_	Date: _		
NCR:			WORK ORDE	R NON-CONFORM	MANCE	(NCF	₹)				
		Description of NC	Corrective Action Section			Section B V		ation	Approval	Approva	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	) 	Sign a	& Section		Chief Eng	QC Inspect	
								ı			
					· · · · · · · · · · · · · · · · · · ·						
				**************************************		<b></b>		1		<b></b>	

Work Order ID 60973 Tuesday, August 03, 2010 9:21:12 AM Item ID: D4017-5 Page 2 **Revision ID:** Accept Item Name: Setup Hinge Rib Start Start Date: 8/4/2010 Start Qty: 2.00 Stop Required Date: 8/6/2010 Req'd Qty: 2.00 Cust Item ID: Reference: Customer: Approvals: Process Plan: \_\_\_\_\_ Date: \_\_\_\_ Tooling: Run QC: Start Date: Date: SPC (Y/N): Sequence ID/ Date: Stop Operation Work Center ID Description Set Up/ Tool ID Tool # Plan 130 Run Hours Accept QC21- Final Inspection - Work Order Release Reject Reject Insp. Code Qty 0.00 Qty. Number Stamp Memo **Quality Control** 0.00

N 10-8-09

Dart Ae	rospace	Ltd							æ	
W/O:			WO	RK ORDER CHANGE	S					
DATE	STEP	PROCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector		
								: 		
Part No	):	PAR #:	Fault Cate	gory:	NCR: Yes	No <b>DQA</b> :		Date: _		
	Re	esolution:	Disposition	QA: N/C Cld	QA: N/C Closed:			Date:		
NCR:		1	WORK ORDE	ER NON-CONFORMA	NCE (NCR	)				
	T	Description of NC	of NC Corrective Actio		on Section B Ver			Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	n &   Section		Chief Eng	QC Inspecto	

## **Picklist Print**

Tuesday, August 03, 2010 9:21:11 AM

Work Order ID: 60973

Parent Item: D4017-5

Parent Item Name: Hinge Rib



Last

Location

Start Date: 8/4/2010

Start Qty: 2.00

Qty per Kit

4.604

Total

9.692632

Qty

Qty

Issued

Required Date: 8/6/2010

Date

Issued

Status

Required Qty: 2.00

Comments:

IPP RevA: new issue DD 09.11.26 verified by:EC

per dwg RevA DD 1

DD 10.04.16 verifie

Replacement Item ID		Bin Prim	 	
er dwg RevA DD D 10.04.16 verifi	10.03.06 ed by:EC	verified by:EC	 IPP Rev: ev:C as per dwg	B as

Item Location

No

Item Name	Replacement Item ID	Mfg/ Purch
M304TS0.750W.049		
304 SQ Tube .75x .75x 040y		Purchased
304 SQ Tube .75x 75x 040y		iii <b>bb</b> iii <b>bibib (bii</b> 1 <b>88</b> )

304 SQ Tube .75x.75x.049W

Component Item ID/

Location  MAT  113763  114323  114677	Loc Oty 40.83646794 0 20.0582189	Loc Cod
114835 MAT017	14.34201 6.436239 3.68448E-05	
114298 WA 114992	3.6845E-05 401.5829 101.5829	
115260	300	

Route

Seq ID

100

Unit of


Measure Hand

Qty on

442.4194

SAD 10-08-04 <u>de</u> 9.6926

Dart Ae	rospace	Ltd							¢.
W/O:			WC	RK ORDER CHANGI	ES			-	
DATE STEP		PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
Part No	):	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA:	1	Date: _	
	Re	esolution:	Dispositio	າ:	QA: N/C C	losed:	_	Date: _	
NCR:			WORK ORDI	ER NON-CONFORMA	NCE (NCF	₹)			
		Description of NC		on B	Verification		Approval	Approva	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section Section		Chief Eng	QC Inspect
						:	1		
		·						-	
									· ·
							ı		
1			j l		ŀ			1	1



Dart Ae	rospace	e Ltd								¢ -
W/O:			WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector
							-			
Part No: PAR #:		PAR #:	Fault Cateo	jory:	NCI	R: Yes	No <b>DQ</b>	:	Date: _	
		Disposition: C			QA: N/C Closed:			Date:		
NCR:	•		WORK ORDE	R NON-CONFO	RMANCE	(NCF	₹)		<del></del>	
		Description of NC	Corrective Action		Section B			ation	Approval	Approva
DATE	STEP	Section A	Initial Chief Eng	Action Descript Chief Eng	ion	Sign 8 Date	🖁   Section		Chief Eng	QC Inspecto
								I		
								-		
								<b> </b>		